



# COPZ – COST

## Data connectors tools

## for coaxial RF contacts

Item	Description	Part No.
	Manual crimping tool for <b>CX 50 R</b> and <b>CX 75 R</b> coaxial contacts	<a href="#">COPZ</a>
	Coaxial cable stripper for the preparation of the cable according to the drawing	<b>COST</b>

### Crimping instructions

- 1) Strip the cable as per drawing using the tool **COST**.
- 2) Crimp the central contact of coaxial connector in the correct crimping area with the position 0,72 of crimping tool **COPZ**.
- 3) Insert the brass back end on the cable.
- 4) Insert the central contact in the coaxial connector, put the braid shield around the back cylinder of contact.
- 5) Insert the brass back end on the braid shield.
- 6) Crimp the ferrule with position 3,25 of crimping tool **COPZ**.

- It is recommended to use coding pins **CRM CX / CRF CX**;
- fit the brass tube on the cable;
- as alternative to crimping, it is possible to solder the central contact.



Tutorial

Contacts	Pages
CX 50 R	C.80
CX 75 R	C.80